

# Oil Field Environmental Incident Summary

**Incident:** 20170621090749 **Date/Time of Notice:** 06/21/2017 09:07

**Responsible Party:** LIME ROCK RESOURCES III-A, L.P.

**Well Operator:** LIME ROCK RESOURCES III-A, L.P.

**Well Name:** CABERNET SWD 1

**Field Name:** CABERNET

**Well File #:** 90174

**Date Incident:** 6/20/2017

**Time Incident:** 09:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 144

**Rng:** 97

**Sec:** 34

**Qtr:**

**Location Description:**

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
1111 BAGBY, SUITE 4600  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	13	Barrels	13	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/11/2017

**Clean Up Concluded:** 6/28/2017

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

The standing fluid was recovered and SM fencing will be dispatched to remove all remaining contaminated material. The gasket has been replaced.

**Wastes Disposal Location:** Chimeny Butte

**Agencies Involved:**

### **Updates**

---

**Date:** 6/21/2017    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary this spill remained on location. NDIC retains oversight.